

Mech. Cert. # or Repair Station #

34635221A

AERO SERVICES, INC.

PROPELLER LOG

Ye

Da

Ne


Du

DATE: 09-11-25 REG. # N536JR SER. # 34033K W.O. 25171

TACH: 0280.3 HOBBS: 2666.0 TSN: 1560.0 TSO: N/A

INSPECTED THIS PROPELLER FOR AN ANNUAL INSPECTION. I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

ROBERT F. McDOWELL III



3463522IA

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

Year: _____	Total Time in Service
Date: _____	
Next Inspection Due: _____	Time Since Overhaul

Year: _____	Total Time in Service
Date: _____	
Next Inspection Due: _____	Time Since Overhaul

Year: _____	Total Time in Service
Date: _____	
Next Inspection Due: _____	Time Since Overhaul